


03500.017683

CORC
IFW
PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	
	:	Examiner: A. Chen
KOHEI MURAYAMA, et al.)	
	:	Group Art Unit: 2182
Appl. No.: 10/670,300)	
	:	
Filed: September 26, 2003)	
	:	
For: CONTROL METHOD FOR BUS)	
PROVIDED WITH INTERNAL SWITCH	:	
)	
U.S. Patent No.: 7,386,634 B2	:	
)	
Issued: June 10, 2008	:	January 21, 2009

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

The following minor errors have been noted in the above-identified patent:

COLUMN 2:

Line 48, "nop_maskp" should read -- oop_maskp --.

COLUMN 4:

Line 6, "salve" should read -- slave --; and

Line 28, "y_one-not-two" should read -- y_one_not_two --.

COLUMN 5:

Line 40, "y_wr_bytenp" should read -- y_wr_byteenp --.

Column 7:

Line 42, "dose" should read -- does --.


Column 9:

Line 18, "establish" should read -- establishes --.

These errors appear to be relatively insignificant and, therefore, we do not believe it is necessary to request a Certificate of Correction. However, it is requested that this paper be placed in the filewrapper of the above-identified patent.

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should be directed to our new address given below.

Respectfully submitted,



Michael K. O'Neill
Attorney for Patentees
Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200